# TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Reason For Inspection:

st Weekly

2nd Weekly

DATE: //. 14.11 State Route (SR) / US Route or Road Name and Description: Are corrective actions required by this inspection report (Y/N): NO Wolf River Blvd. County(ies) TDOT PIN: NPDES Permit (NOC) #: Number of New Number of Recurring Number of New Number of Un-Corrected Corrective Actions: Corrective Actions: Sediment Releases: Sediment Releases: Shelby 101615 TNR153299 TDOT Construction No.: TDOT Contract No.: Contractor: 0 0 7994-1535-54 Acuff Enterprises Inc. I certify, under penalty of law that this document and all attachments were COG EPSC Inspector and Title (print or type): Signature: prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated Gerald "Jerry" Stanfill information presented. Based on my inquiry of the person or persons who, manage the system, or those persons directly responsible for gathering the Contractor EPSC Inspector and Title (print or type): information, I cerify that inspections of storm water discharge points (outfalls), and of erosion and sediment controls have been performed as recorded in the table Tom'Acuff above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as recorded in the table above I am aware that there are significant penalties for COG EPSC Project Manager submitting false information, including the possibility of fine and impresonment for (print or type): knowing violations Timothy Bierdz TDOT EPSC Inspection Weekly Rainfall Data Log Predicted TDOT/Contractor Agrees with Inspection Report: Rainfall Rainfall Rainfall Rainfall Rainfall Rainfall Day of Week Date Precipitation Gauge 1 Duration NO (YES Gauge 2 Gauge 3 Gauge 4 Gauge 5 Gauge 6 (%) (hr) If No, explain and initial: (in) (in) (in) (in) (in) (in) 11.13.11 Sunday N/A 10 N/A N/A N/A 11.14.11 Monday 30 0 0 N/A N/A N/A N/A 11-15-11 Tuesday 80 N/A N/A N/A N/A Wednesday 50 N/A N/A N/A N/A 11-17-11 Thursday N/A N/A 0 N/A NIA 11.11.11 Friday N/A N/A N/A 0 N/A 11.12.11 Salurday 0 N/A N/A N/A N/A Sunday N/A N/A N/A N/A Monday N/A N/A N/A N/A (Additional pages may be attached, if needed)

Predicted Precipitation Source:

www.wealher.com

Page 1 of 7

زد	ÖE	THE	877	<u>*.</u>
	AGR	CUL	EURI	
	100	AME		
•	<b>//</b>	796	: 32	

State/US Route or Road Name:	Wolf River Blvd.	TDOT C

Construction No.: 79954-3537-54

70054	252	7 . 4
79954	-303	1-04

TDOT Contract No.:

**CONDITION CODES** 

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	11/14/2011		22,35	FM	Weekly cleaning will be required, until further notice.
1A	1	21+50	RT	11/14/2011		41	FM	Const. of RCBC Pedestrian Underpass in progress.
1B	1	22+00	RT	11/10/2011		41	FM	No activity during this inspection.
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,35,41	FM	Monitoring BMP's in place.
2A	11	33+50	LT,CL	11/14/2011		12,15,16,24	FM	Monitoring BMP's in place.
2B	1	35+50	LT	11/14/2011		16,24	FM	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	FM	Monitoring BMP in place.
4	11	40+00	RT	11/7/2011	T = 10-24-11	15,16,43	FM	Monitoring BMP's in place.
5A	1	49+00	RT	10/24/2011		16,33	FM	Monitoring BMP's in place.
5B	1	50+00	RT	10/24/2011		9,16,33	FM	Monitoring BMP's in place.

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	I	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	
				43	Stream Realignment		

13	Ň.		
1	0	١.	
E	1	ŀ	
	lii,	1	
1	15	/:	
4	₃/,	•	

State/US	Route or	Road	Name

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	11/14/2011

Outfall Name or Station No.	Rain Gage	Approx. Station No.	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code	Existing EPSC Control	Current Condition	Corrective Action(s) or Comments
	No.	From / To			T = Temp. P = Perm.	Measure Codes*	Codes*	
5C	1	44+00	LT	11/14/2011		16,24,33	FM	Weekly cleaning for stream crossing required. (A section of BMP's needs to be completed along top of north bank @ New Channel Realignment).
6	1	56+00	LT	10/24/2011	,	10,24,33	FM	Pond to be re-drained at a future date.  Currently Stable.
7	1	60+00	RT	10/24/2011		16, 33	FM	Currently Stable, Monitoring BMP's.
8A	1	73+00	RT	11/14/2011		16,24,42	FM	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	FM	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	11/14/2011		16,35,42	FM	Active construction zone. Monitoring BMP's.
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	FM	Monitoring BMP's. Weekly watering required until seed establishes.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	FM	Weekly watering required until seed establishes.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	FM	Weekly watering required until seed establishes.

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier 1 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 4 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing Cleaning Needed Sediment Removal 20 6 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 8 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 S 11 Gabion Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Other (O#2): Haul Road Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

**CONDITION CODES** 

۴			
ò	۱		
7	1	•	
Ш	7	1	
L	إن	•	
⋖	/	•	

State/US Route or Road Name:

	10	D.		
vvo	IT	Rive	er B	ıva.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	11/14/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	FM	Weekly watering required until seed establishes.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM	Monitoring BMP's in place.
10B	2	85+00	RT	9/29/2011		15,16,35,41	FM	Monitoring BMP's in place.
10C	2	85+50	LT	11/14/2011		15,16,35,41	FM	BMP's are required. See Photo
10D	2	84+50	LT	11/14/2011		15,16,35,41	FM	BMP's are required. See Photo
11A	2	92+50	RT	11/14/2011		35,41	FM	Monitoring BMP's in place.
11B	2	92+50	LT	10/6/2011		10,32,35,41	FM	Remove forms when accessible. See photo
11C	2	92+00	LT	10/6/2011		10,32,35,41	FM	Remove forms when accessible. See photo
	1	11+28	LT	11/14/2011		19,35	FM	Daily cleaning is required, until further notice
	1	13+40	RT	11/14/2011		23,29,30	FM	Daily cleaning will be required, until furthe notice.
	1	107+75	CL NAND SEDIME	11/14/2011	MEASURE CODES	23,29,30	FM	Daily cleaning will be required, until furthe notice.  CONDITION CODES

### EROSION AND SEDIMENT CONTROL MEASURE CODES

### Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch Haul Roads Dampened for Dust Control 30 Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams Rock Silt Screen 18 Flexible Channel Liner 32 FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing 33 С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 **Temporary Stream Crossing** 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap Other (O31): 12 26 40 Temporary Stream Diversion Sheet Pilling 13 Geotextile 27 Haul Road Preserve Natural Resource / Buffer Zone 41 Other (O#2): Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade 14 **Bridge Construction** Other (O#3):

State/US Route or Road Name:	

Molf	River	Dlyd
VVOIT	River	BIVa

TDOT Construction No.: 79954-3537-54

79	95	4-3	53	7-54

TDOT Cor	stract No :	
IDOI Cor	itract No.:	

Date	11/14/2011

0.45-11.11	D .:		1 - 5 -		Date of	Existing		
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
*(Existing	No.	From / To			T = Temp.	Measure	Codes*	
Structure)					P = Perm.	Codes*		
								Daily cleaning will be required, until further
* 109+51	2	East side of WRB	RT	11/14/2011		19,22	FM	notice.
		South side of						Daily cleaning will be required, until further
* 109+11	2	Farmington	RT	11/14/2011		19,22	FM	notice.
		North side of						Daily cleaning will be required, until further
* 12+80	1	WRB	LT	11/14/2011		19,22	FM	notice.
		Walking Trail						
	1	36+00	LT	7/20/2011	T = 7-20-11	5,35	FM	Currently stable, Monitoring BMP's
						-,		, canalage and general
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	FM	Currently stable.
		Sta. 13+40 -		11				Haul roads dampened frequently for dust
		Sta. 107+75	LT, RT or CL	10/13/2011	1	30	FM	control, until further notice.
			<del></del>					
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed establishes.
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	FM	Mookh, watering required until good actablishes
		32130 - 107100	L l	3/23/2011	1 - 10-03-11	15, 16,55	LIVI	Weekly watering required until seed establishes.
	4	0.75		44/44/0044		40.00	E14	Daily cleaning will be required, until further
		6+75	LT	11/14/2011		19,22	FM	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	FM	Currently stable, Monitoring BMP's
	1	34+00	RT	8/25/2011	T= 8-25-11	16	FM	Currently stable, Monitoring BMP's
		EROSI	ON AND SEDIMEN	T CONTROL ME	ASURE CODES			CONDITION CODES

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier 1 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain **Erosion Control Blanket** 17 31 Ditch Liner R Replacement Needed Rock Check Dams 4 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 8 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 FS Berm (soil, riprap, rock) Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion Sheet Pilling Other (O31): 27 Other (O#2): 13 Geolextile Preserve Natural Resource / Buffer Zone Haul Road 41 Permanent Seeding with Mulch or Sod 14 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):



0 id Name:	Wolf River Blvd.	TDOT Construction No.;	79954-3537-54	TDOT Contract No.:

Date	11/14/2011

Outfall Name	Rain	Approx.	LT, RT or	Date Last	Date of Stabilization	Existing EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
	No.	From / To			T = Temp.	Measure	Codes*	
					P = Perm.	Codes*		
	1	21+33 - 26+00	LT	10/10/2011	T = 10 C 11	45 40 25 44	ENA	Weekly watering required until seed
		21733 - 20700	L!	10/10/2011	T = 10-6-11	15,16,35,41	FM	establishes.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed establishes.
	1	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	FM	Currently stable, monitoring BMP's.
	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	FM	Currently stable, monitoring BMP's. Weekly watering required until seed establishes.
* 108+37		North side of WRB	LT	11/14/2011		19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	FM	Currently stable, monitoring BMP's.
						110000		

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### **CONDITION CODES** Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal Riprap Outlet Structure 20 Enhanced Silt Fence Increase Measures 7 Straw Bale Check Riprap Energy / Velocity Dissipater 21 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues Sediment Release 10 Temp Sediment Filter Bag / Dewatering Temporary Stream Crossing 24 38 Berm (soil, riprap, rock) Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 S Gabion Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion Other (O31): 40 Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod 14 28 Mineral Aggregate Base on Sub grade **Bridge Construction** Other (O#3):





City of Germantown 1920 S. Germantown Road Germantown, TN 38138